ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
14

Ward Name
Bagalakunte

Street ID
W0833, W0839, W0648

Street Name
NA

Significant Landmark
Defence colony

Segment No.
14/C-W0833/S022328

Total Length (m)
146.23

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	146.23	77.506482	13.051545	77.507827	13.051454	Hesaraghatta Main Road	w0833

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to drains at 1st A Main R/S Defence colony

Sanctioned Estimated Amount (Rs.)
400000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Drain Maintenance

Other Work Type

Tender
Not a Tender

Work Details

Job No. / Work Code
014-15-000035

Work Order No.
EE/DD/WO/244/14-15

Work Order Date
09/02/2015

Period of Extention

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
396959.00

Phone No.
8197839023

E-Mail ID

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0833, W0839, W0648

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Manjunath

Date of Inspection	Remarks
25/07/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	25/07/2016	24/08/2016	COMPLETED
EE	SRINIVAS	25/07/2016	24/08/2016	COMPLETED
AEE	RANGA SWAMY	25/07/2016	24/08/2016	COMPLETED
AE	MANJUNATH	25/07/2016	24/08/2016	COMPLETED
AE	MANJUNATH	25/07/2016	24/08/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0833, W0839, W0648